



Tuesday, February 27, 2024

AXIS Firmware Update Available Version 3.4.0.20240201

A new firmware update for the AXIS Service Interface is available for AXIS users. Here are the new features and improvements included in this release.

Software Updates:

- Bugfixes
- Restoration of ECU firmware flashing log event
- Changes to default timeout values to improve user experience
- Added support for the use of value ranges within state widgets

Machine Support Updates:

- AD108E and EP20
- Rail features: AT41ME and AT41SE
- AC65E above and below rotation
- AH125B AH150B primary ECM
- JEMS LE Freightliner Plus
- JEMS DC 2020 Ford chassis

To update your AXIS Service Interface with the latest firmware, follow these steps:

- Visit www.altec.com/axis and select DOWNLOADS from the menu
- Download and save the firmware file (ending in 3.4.0.20240201) to a convenient location on your computer or mobile device
- Power your AXIS device
- Connect your computer or mobile device to AXIS and navigate to the Login page
- Select "Update Firmware" from the Guest Menu
- Browse to and select the locally saved firmware file (ending in 3.4.0.20240201) and follow instructions on the device

For additional support, please contact the AXIS support team at axis.support@altec.com.

Sincerely,
The AXIS Support Team

Copyright 2024 Altec Industries, Inc. All rights reserved. **This document** (including any attachments) **contains confidential information** intended for a specific individual and purpose and is protected by law. If you are not the intended recipient, you should delete this message. Any disclosure, copying, or distribution of this message, or the taking of any action based on it without prior written consent, is strictly prohibited.