



---

June 4, 2019

## AXIS Firmware Update Available Version 2.0.30916

A new firmware for the AXIS Service Interface is now available for AXIS users.

New features and improvements in the new release include:

- AH75, AH85, and AH100
- AH75B, AH85B, and AH100B
- AD108E
- Aerial platform and boom load monitoring systems

To update your AXIS Service Interface with this latest firmware, follow these steps:

- Visit [www.altec.com/axis](http://www.altec.com/axis) and select DOWNLOADS from the menu.
- Download and save the firmware file (ending in 2.0.30916) to a convenient location on your computer or mobile device.
- Power your AXIS device
- Connect your computer or mobile device to AXIS and navigate to the Login Page
- Select "Update Firmware" from the Guest Menu
- Browse-to and select the locally saved firmware file (ending in 2.0.30916) and follow instructions on the device

For additional support, please contact the AXIS support team at [axis.support@altec.com](mailto:axis.support@altec.com)

Sincerely,

The AXIS Support Team