



Thursday, April 09, 2020

AXIS Firmware Update Available Version 2.1.3.39337

A new firmware update for the AXIS Service Interface is available for AXIS users.

New features and improvements included in this release include:

- AH75B, AH85B, & AH100B - Upper and Lower Controls
- DHE, DT65, D3000E - E-Series Derrick Controls
- JEMS DC - 2020 Ford Chassis support
- JEMS DC - Single Manual Start Option
- DB41 – HOP System Update Firmware (Supports CSN 755)

To update your AXIS Service Interface with the latest firmware, follow these steps:

- Visit www.altec.com/axis and select DOWNLOADS from the menu
- Download and save the firmware file (ending in 2.1.3.39337) to a convenient location on your computer or mobile device
- Power your AXIS device
- Connect your computer or mobile device to AXIS and navigate to the Login Page
- Select “Update Firmware” from the Guest Menu
- Browse to and select the locally saved firmware file (ending in 2.1.3.39337) and follow instructions on the device

For additional support, please contact the AXIS support team at axis.support@altec.com.

Sincerely,

The AXIS Support Team