



Tuesday, April 06, 2021

AXIS Firmware Update Available

Version 2.4.0.48674

A new firmware update for the AXIS Service Interface is available for AXIS users. Here are the new features and improvements included in this release.

Updated the content for:

- DH-E, D3000E, DT65/85 E-series
- AT238P
- AM & AA High Slope Operations
- AH75/85/100 B-series
- AT 37/41/48 ME/PE/SE
- LS49

Added support for:

- Lanyard Detection System
- JEMS S/SE on Ford, International & Freightliner
- JEMS LE on International & Freightliner
- JEMS S/SE/LE battery pack

To update your AXIS Service Interface with the latest firmware, follow these steps:

- Visit www.altec.com/axis and select DOWNLOADS from the menu
- Download and save the firmware file (ending in 2.4.0.48674) to a convenient location on your computer or mobile device
- Power your AXIS device
- Connect your computer or mobile device to AXIS and navigate to the Login page
- Select "Update Firmware" from the Guest Menu
- Browse to and select the locally saved firmware file (ending in 2.4.0.48674) and follow instructions on the device

For additional support, please contact the AXIS support team at axis.support@altec.com.

Sincerely,

The AXIS Support Team