



Wednesday, August 04, 2021

AXIS Firmware Update Available Version 2.4.2.52025

A new firmware update for the AXIS Service Interface is available for AXIS users. Here are the new features and improvements included in this release.

Machine Support Updates:

- AT 41/48
- AN50/55-OC
- AC40/45E
- AH125S-A
- Aerial Load Monitoring System (ALMS)
- Below Rotation Integration Module (BRIM)

To update your AXIS Service Interface with the latest firmware, follow these steps:

- Visit www.altec.com/axis and select DOWNLOADS from the menu
- Download and save the firmware file (ending in 2.4.2.52025) to a convenient location on your computer or mobile device
- Power your AXIS device
- Connect your computer or mobile device to AXIS and navigate to the Login page
- Select "Update Firmware" from the Guest Menu
- Browse to and select the locally saved firmware file (ending in 2.4.2.52025) and follow instructions on the device

For additional support, please contact the AXIS support team at axis.support@altec.com.

Sincerely,

The AXIS Support Team