



Wednesday, September 08, 2021

AXIS Firmware Update Available Version 2.4.3.52990

A new firmware update for the AXIS Service Interface is available for AXIS users. Here are the new features and improvements included in this release.

Machine Support Updates:

- AT41/48 MW
- AC4xE
- AT238P
- AT335
- LS49
- E-Series Digger Derricks
- JEMS S/SE/LE
- Lanyard Detection System
- High Slope and Load Monitoring System
- Dual-Encoder Rotation Protection System

To update your AXIS Service Interface with the latest firmware, follow these steps:

- Visit www.altec.com/axis and select DOWNLOADS from the menu
- Download and save the firmware file (ending in 2.4.3.52990) to a convenient location on your computer or mobile device
- Power your AXIS device
- Connect your computer or mobile device to AXIS and navigate to the Login page
- Select "Update Firmware" from the Guest Menu
- Browse to and select the locally saved firmware file (ending in 2.4.3.52990) and follow instructions on the device

For additional support, please contact the AXIS support team at axis.support@altec.com.

Sincerely,

The AXIS Support Team