



Wednesday, November 03, 2021

AXIS Firmware Update Available Version 2.7.0.54445

A new firmware update for the AXIS Service Interface is available for AXIS users. Here are the new features and improvements included in this release.

Feature Updates:

- Persistent content bugfix

Machine Support Updates:

- AM & AN High Slope Operation
- AN & AT41/48ME Aerial Load Monitoring System
- AT41 Rotation Interlock System
- E-Series Cranes
- JEMS DC
- LS49
- DSC6
- DC610

To update your AXIS Service Interface with the latest firmware, follow these steps:

- Visit www.altec.com/axis and select DOWNLOADS from the menu
- Download and save the firmware file (ending in 2.7.0.54445) to a convenient location on your computer or mobile device
- Power your AXIS device
- Connect your computer or mobile device to AXIS and navigate to the Login page
- Select "Update Firmware" from the Guest Menu
- Browse to and select the locally saved firmware file (ending in 2.7.0.54445) and follow instructions on the device

For additional support, please contact the AXIS support team at axis.support@altec.com.

Sincerely,

The AXIS Support Team