



Thursday, February 01, 2024

AXIS Firmware Update Available Version 3.3.2.20240101

A new firmware update for the AXIS Service Interface is available for AXIS users. Here are the new features and improvements included in this release.

Software Updates:

- Bugfixes and new Altec icon set.

Machine Support Updates:

- AC40E above rotation PCM
- E-Series Derricks below rotation
- LP108-ES, EP20, and AD108E
- Navistar eMV Altec controls

To update your AXIS Service Interface with the latest firmware, follow these steps:

- Visit www.altec.com/axis and select DOWNLOADS from the menu
- Download and save the firmware file (ending in 3.3.2.20240101) to a convenient location on your computer or mobile device
- Power your AXIS device
- Connect your computer or mobile device to AXIS and navigate to the Login page
- Select "Update Firmware" from the Guest Menu
- Browse to and select the locally saved firmware file (ending in 3.3.2.20240101) and follow instructions on the device

For additional support, please contact the AXIS support team at axis.support@altec.com.

Sincerely,
The AXIS Support Team