



Saturday, March 1st, 2025

AXIS Firmware Update Available Version 3.4.5.20250301

A new firmware update for the AXIS Service Interface is available for AXIS users. Here are the new features and improvements included in this release.

Bug Fixes:

- **Important:** Please update your AXIS Service Interface to AXIS version 3.4.5 as soon as practical. An issue was found with the date stamps in version 3.4.3 & 3.4.4 and must be replaced with this version.

Machine Support Updates:

- Added support for JEMS S/SE, 2019 Ford chassis
- Added support for BRIM (Below Rotation Integration Module)
- Added support for JEMS S/SE, 2021+ CV515 chassis
- Updated support for AT40G, AT238P & AT335
- Updated support for AC40E & AC45E - Above Rotation PCM
- Updated support for D3, DH & DT models of the E-Series Derrick
- Updated support for Aerial Boom and Platform Load Monitoring System

To update your AXIS Service Interface with the latest firmware, follow these steps:

- Visit www.altec.com/axis and select DOWNLOADS from the menu
- Download and save the firmware file (ending in 3.4.5.20250301) to a convenient location on your computer or mobile device
- Power your AXIS device
- Connect your computer or mobile device to AXIS and navigate to the Login page
- Select "Update Firmware" from the Guest Menu
- Browse to and select the locally saved firmware file (ending in 3.4.5.20250301) and follow instructions on the device

For additional support, please contact the AXIS support team at axis.support@altec.com.

Sincerely,
The AXIS Support Team