



Wednesday, August 6, 2025

AXIS Firmware Update Available

Version 3.6.1.20250808

A new firmware update for the AXIS Service Interface is available for AXIS users.

Software Update:

- Added CAN switch feature.
- Fixed performance issues.

Machine Support Updates:

- AC45E, AC65E
- DME, DHE, D3E, DT65E, DT85E, DT85E-TC
- LP108-ES
- Below Rotation Integration Module (BRIM)
- Dual Encoder Rotation Protection System
- AH125B, AH150B (and added A2L support)
- AT238P
- AT335
- AT37/41/48 ME/PE/SE
- AT41SE Rail Features
- JEMS S/SE with International DLB
- Below Rotation Integration Module (BRIM)
- Trailer Plug Tester
- PDM-6A
- Rail Features (AT41ME)
- LS
- PDM-6A-HD-250K

To update your AXIS Service Interface with the latest firmware, follow these steps:

- Visit altec.com/axis and select DOWNLOADS from the menu
- Download and save the firmware file (ending in 3.6.1.20250808) to a convenient location on your computer or mobile device
- Power your AXIS device
- Connect your computer or mobile device to AXIS and navigate to the Login page
- Select "Update Firmware" from the Guest Menu
- Browse to and select the locally saved firmware file (ending in 3.6.1.20250808) and follow instructions on the device

For additional support, please contact the AXIS support team at axis.support@altec.com.

Sincerely,
The AXIS Support Team

Copyright 2025 Altec Industries, Inc. All rights reserved. **This document** (including any attachments) **contains confidential information** intended for a specific individual and purpose and is protected by law. If you are not the intended recipient, you should delete this message. Any disclosure, copying, or distribution of this message, or the taking of any action based on it without prior written consent, is strictly prohibited.