



Monday, February 2, 2026

AXIS Firmware Update Available

Version 3.9.0.20260201

A new firmware update for the AXIS Service Interface is available for AXIS users. Here are the new features and improvements included in this release.

Software Updates:

- Fixed icon scaling.

Machine Support

- AA55+, AN55+
- AH75B, AH85B, AH100B, AH125B, AH150B
- AT238P, AT335, AT40G
- DME, DHE, D3E, DXE, DT65E, DT85E, DT85E-TC
- EP20
- JEMS DC Plus
- JEMS LE - Freightliner and Freightliner Plus Chassis, International DLB & Kenworth Chassis
- JEMS S/SE - Ford, RAM, CV515, International and International DLB, & Freightliner Chassis
- LP108

Equipment Feature Updates:

- Lanyard Detection & Outlet Detection
- LevelReady & High Slope
- PDM-6A-HD-250K

To update your AXIS Service Interface with the latest firmware, follow these steps:

- Visit www.altec.com/axis and select DOWNLOADS from the menu
- Download and save the firmware file (ending in 3.9.0.20260201) to a convenient location on your computer or mobile device
- Power your AXIS device
- Connect your computer or mobile device to AXIS and navigate to the Login page
- Select "Update Firmware" from the Guest Menu
- Browse to and select the locally saved firmware file (ending in 3.9.0.20260201) and follow instructions on the device

For additional support, please contact the AXIS support team at axis.support@altec.com.

Sincerely,
The AXIS Support Team