



July 20, 2018

AXIS Firmware Update Available Version 2.0.22469

A new firmware for the AXIS Service Interface is now available for AXIS users.

New features and improvements included in the new release include:

- Added Machine support for
 - Altec model DB37 Updates
 - Altec model AM Updates
- Updates
 - Altec model MT-60E70
- New Features
 - Pencil Icon added to indicate modifiable text and values
 - About Page displays information about user, axis hardware, and axis firmware
 - QR code is generated for unit serial number

To update your AXIS Service Interface with this latest firmware, follow these steps:

- Visit www.altec.com/axis and select DOWNLOADS from the menu.
- Download and save the firmware file (ending in 2.0.22XXX) to a convenient location on your computer or mobile device.
- Power your AXIS device
- Connect your computer or mobile device to AXIS and navigate to the Login Page
- Select "Update Firmware" from the Guest Menu
- Browse-to and select the locally saved firmware file (ending in 2.0.22XXX) and follow instructions on the device

For additional support, please contact the AXIS support team at axis.support@altec.com

Sincerely,

The AXIS Support Team