



Friday, June 12, 2020

AXIS Firmware Update Available Version 2.1.4.40683

A new firmware update for the AXIS Service Interface is available for AXIS users.

New features and improvements included in this release :

- Aerial Load Monitoring System
- Aerial High Slope Operation System

To update your AXIS Service Interface with the latest firmware, follow these steps:

- Visit www.altec.com/axis and select DOWNLOADS from the menu
- Download and save the firmware file (ending in 2.1.4.40683) to a convenient location on your computer or mobile device
- Power your AXIS device
- Connect your computer or mobile device to AXIS and navigate to the Login Page
- Select "Update Firmware" from the Guest Menu
- Browse to and select the locally saved firmware file (ending in 2.1.4.40683) and follow instructions on the device

For additional support, please contact the AXIS support team at axis.support@altec.com.

Sincerely,

The AXIS Support Team