



Tuesday, July 06, 2021

AXIS Firmware Update Available Version 2.4.2.51382

A new firmware update for the AXIS Service Interface is available for AXIS users. Here are the new features and improvements included in this release.

Machine Support Updates:

- AT335 (New Model)
- Aerial Load Monitoring System
- AT238P
- AN50/66-0C (High Slope Operation)
- AH125S-A
- AH150 (Outrigger Alarm)
- AC40E/AC45E
- DRM12
- E-Series Cranes (Chassis Interface)
- E-Series Derricks
- JEMS (S/SE/LE)

To update your AXIS Service Interface with the latest firmware, follow these steps:

- Visit www.altec.com/axis and select DOWNLOADS from the menu
- Download and save the firmware file (ending in 2.4.2.51382) to a convenient location on your computer or mobile device
- Power your AXIS device
- Connect your computer or mobile device to AXIS and navigate to the Login page
- Select "Update Firmware" from the Guest Menu
- Browse to and select the locally saved firmware file (ending in 2.4.2.51382) and follow instructions on the device

For additional support, please contact the AXIS support team at axis.support@altec.com.

Sincerely,

The AXIS Support Team