



Wednesday, February 09, 2022

AXIS Firmware Update Available Version 2.8.2.55958

A new firmware update for the AXIS Service Interface is available for AXIS users. Here are the new features and improvements included in this release.

Machine Support Updates:

- AH75B AH85B AH100B Lower Controls Primary ECM
- AH75B AH85B AH100B Upper Controls Primary ECM
- AT41/48 ME Aerial Load Monitoring System
- AT41/48 MW/PW Above Rotation
- Smart Zone System
- Voice Alarm System

To update your AXIS Service Interface with the latest firmware, follow these steps:

- Visit www.altec.com/axis and select DOWNLOADS from the menu
- Download and save the firmware file (ending in 2.8.2.55958) to a convenient location on your computer or mobile device
- Power your AXIS device
- Connect your computer or mobile device to AXIS and navigate to the Login page
- Select "Update Firmware" from the Guest Menu
- Browse to and select the locally saved firmware file (ending in 2.8.2.55958) and follow instructions on the device

For additional support, please contact the AXIS support team at axis.support@altec.com.

Sincerely,

The AXIS Support Team