



Tuesday, April 05, 2022

AXIS Firmware Update Available Version 2.8.3.57460

A new firmware update for the AXIS Service Interface is available for AXIS users. Here are the new features and improvements included in this release.

Machine Support Updates:

- AD108E
- AT 41/48 MW/PW
- AC40E, AC45E
- D3000E, DHE, DM, DT65, DT65E, DT85, DT85E
- JEMS LE - Freightliner Chassis, International Chassis, International DLB
- JEMS S/SE - 2019 Ford, 2020 Ford, 2020 RAM, Freightliner, International
- LS49
- Aerial Load Monitoring System
- Dual Encoder Rotation Protection System
- Voice Alarm System

To update your AXIS Service Interface with the latest firmware, follow these steps:

- Visit www.altec.com/axis and select DOWNLOADS from the menu
- Download and save the firmware file (ending in 2.8.3.57460) to a convenient location on your computer or mobile device
- Power your AXIS device
- Connect your computer or mobile device to AXIS and navigate to the Login page
- Select "Update Firmware" from the Guest Menu
- Browse to and select the locally saved firmware file (ending in 2.8.3.57460) and follow instructions on the device

For additional support, please contact the AXIS support team at axis.support@altec.com.

Sincerely,

The AXIS Support Team