



Friday, July 15, 2022

AXIS Firmware Update Available Version 2.8.4.59017

A new firmware update for the AXIS Service Interface is available for AXIS users. Here are the new features and improvements included in this release.

Machine Support Updates:

- AT 37/41/48 ME/PE/SE
- AH75B AH85B AH100B
- AT335
- E-Series Derricks (DHE, D3000E, DT65E, DT85E)
- E-Series Cranes
- AC45E
- AC40E
- AT 41/48 MW/PW
- Winch Lockout Custom Option
- PDM-6A
- JEMS S/SE 2021+ CV515 CHASSIS

To update your AXIS Service Interface with the latest firmware, follow these steps:

- Visit www.altec.com/axis and select DOWNLOADS from the menu
- Download and save the firmware file (ending in 2.8.4.59017) to a convenient location on your computer or mobile device
- Power your AXIS device
- Connect your computer or mobile device to AXIS and navigate to the Login page
- Select "Update Firmware" from the Guest Menu
- Browse to and select the locally saved firmware file (ending in 2.8.4.59017) and follow instructions on the device

For additional support, please contact the AXIS support team at axis.support@altec.com.

Sincerely,

The AXIS Support Team