



Tuesday, September 06, 2022

AXIS Firmware Update Available Version 3.0.1.20220901

A new firmware update for the AXIS Service Interface is available for AXIS users. Here are the new features and improvements included in this release.

Machine Support Updates:

- AD108E
- AP45A Pre-Lasher Ready
- BRIM / Outrigger Interlock
- E-Series Derricks - Below Rotation
- JEMS S/SE 2021+ CV515 CHASSIS

To update your AXIS Service Interface with the latest firmware, follow these steps:

- Visit www.altec.com/axis and select DOWNLOADS from the menu
- Download and save the firmware file (ending in 3.0.1.20220901) to a convenient location on your computer or mobile device
- Power your AXIS device
- Connect your computer or mobile device to AXIS and navigate to the Login page
- Select "Update Firmware" from the Guest Menu
- Browse to and select the locally saved firmware file (ending in 3.0.1.20220901) and follow instructions on the device

For additional support, please contact the AXIS support team at axis.support@altec.com.

Sincerely,

The AXIS Support Team