



Thursday, July 2, 2026

AXIS Firmware Update Available

Version 3.10.0.20260624

A new firmware update for the AXIS Service Interface is available for AXIS users. Here are the new features and improvements included in this release.

Machine Support Updates: [08]

- AC45E, AC40E
- AH75B, AH85B, AH100B, AH125B, AH150B
- AT40G
- DME, DHE, D3E, DT65E, DT85E, DT85E-TC, and DXE
- LR LevelReady Feature
- International eMV
- Peterbilt 567EV
- Below Rotation Integration Module (BRIM)

To update your AXIS Service Interface with the latest firmware, follow these steps:

- Visit www.altec.com/axis and select DOWNLOADS from the menu
- Download and save the firmware file (ending in 3.10.0.20260624) to a convenient location on your computer or mobile device
- Power your AXIS device
- Connect your computer or mobile device to AXIS and navigate to the Login page
- Select "Update Firmware" from the Guest Menu
- Browse to and select the locally saved firmware file (ending in 3.10.0.20260624) and follow instructions on the device

For additional support, please contact the AXIS support team at axis.support@altec.com.

Sincerely,
The AXIS Support Team