



Tuesday, October 31, 2023

AXIS Firmware Update Available Version 3.3.1.20231101

A new firmware update for the AXIS Service Interface is available for AXIS users. Here are the new features and improvements included in this release.

Machine Support Updates:

- E-Series Derricks (DM45/47E, DH45/48/50E, D3050/55/60E, DT65/85E)
- Below Rotation Integration Module (BRIM)
- The AXIS Legacy Gateway

To update your AXIS Service Interface with the latest firmware, follow these steps:

- Visit www.altec.com/axis and select DOWNLOADS from the menu
- Download and save the firmware file (ending in 3.3.1.20231101) to a convenient location on your computer or mobile device
- Power your AXIS device
- Connect your computer or mobile device to AXIS and navigate to the Login page
- Select "Update Firmware" from the Guest Menu
- Browse to and select the locally saved firmware file (ending in 3.3.1.20231101) and follow instructions on the device

For additional support, please contact the AXIS support team at axis.support@altec.com.

Sincerely,
The AXIS Support Team