



Thursday, April 04, 2024

AXIS Firmware Update Available Version 3.4.1.20240401

A new firmware update for the AXIS Service Interface is available for AXIS users. Here are the new features and improvements included in this release.

Software Updates:

- Improvements and Bugfixes

Machine Support Updates:

- AC40E/45E/65E Primary Control Modules
- AH125S-A Primary Control Module (Turntable)
- AH Series Upper Control Module
- AT 37/41/48 ME/PE/SE updates
- Rotation Interlock System updates
- Lanyard Alert System and Lanyard Interlock System Primary Control Modules

To update your AXIS Service Interface with the latest firmware, follow these steps:

- Visit www.altec.com/axis and select DOWNLOADS from the menu
- Download and save the firmware file (ending in 3.4.1.20240401) to a convenient location on your computer or mobile device
- Power your AXIS device
- Connect your computer or mobile device to AXIS and navigate to the Login page
- Select "Update Firmware" from the Guest Menu
- Browse to and select the locally saved firmware file (ending in 3.4.1.20240401) and follow instructions on the device

For additional support, please contact the AXIS support team at axis.support@altec.com.

Sincerely,
The AXIS Support Team