



Wednesday, May 01, 2024

AXIS Firmware Update Available
Version 3.4.2.20240501

A new firmware update for the AXIS Service Interface is available for AXIS users.

Here are the new features and improvements included in this release.

Software Updates:

- Improvements and bugfixes

Machine Support Updates:

- AC45E Below Rotation
- AD108E
- AH125B/AH150B Primary Module
- DT85E/DT65E/DHE/D3E/DME Above Rotation Module
- JEMS S/SE Freightliner Plus Chassis
- LP108-ES
- LS49
- PDM-6A
- TDA58
- Lanyard Interlock System
- Voice Alarm System

To update your AXIS Service Interface with the latest firmware, follow these steps:

- Visit www.altec.com/axis and select DOWNLOADS from the menu
- Download and save the firmware file (ending in 3.4.2.20240501) to a convenient location on your computer or mobile device
- Power your AXIS device
- Connect your computer or mobile device to AXIS and navigate to the Login page
- Select "Update Firmware" from the Guest Menu
- Browse to and select the locally saved firmware file (ending in 3.4.2.20240501) and follow instructions on the device

For additional support, please contact the AXIS support team at axis.support@altec.com.

Sincerely,
The AXIS Support Team