



Wednesday, May 29, 2024

AXIS Firmware Update Available Version 3.4.2.20240601

A new firmware update for the AXIS Service Interface is available for AXIS users. Here are the new features and improvements included in this release.

Machine Support Updates:

- AH125B AH150B Primary Module
- JEMS LE Freightliner Plus
- JEMS LE & S/SE Freightliner Chassis
- JEMS LE 2021 CV515 LS49
- JEMS LE International DLB
- JEMS S/SE 2021+ CV515 CHASSIS
- JEMS S/SE 2020 RAM & Ford
- JEMS S/SE 2019 Ford
- Lanyard Interlock System & Lanyard Alert System

To update your AXIS Service Interface with the latest firmware, follow these steps:

- Visit www.altec.com/axis and select DOWNLOADS from the menu
- Download and save the firmware file (ending in 3.4.2.20240601) to a convenient location on your computer or mobile device
- Power your AXIS device
- Connect your computer or mobile device to AXIS and navigate to the Login page
- Select "Update Firmware" from the Guest Menu
- Browse to and select the locally saved firmware file (ending in 3.4.2.20240601) and follow instructions on the device

For additional support, please contact the AXIS support team at axis.support@altec.com.

Sincerely,
The AXIS Support Team