



Wednesday, July 31, 2024

AXIS Firmware Update Available Version 3.4.2.20240801

A new firmware update for the AXIS Service Interface is available for AXIS users. Here are the new features and improvements included in this release.

Machine Support Updates:

- AH125S-A Primary Turntable ECM
- AH75B AH85B AH100B Upper/Lower Controls
- AH75B AH85B AH100B Upper/Lower Controls Primary ECM
- AT238P & AT335
- E-Series Derricks
- JEMS LE 2021 CV515 LS49
- JEMS LE Freightliner Plus
- JEMS S/SE 2019-2020 Ford
- JEMS S/SE Freightliner Chassis
- JEMS S/SE Freightliner Plus Chassis
- JEMS S/SE International
- LS49

To update your AXIS Service Interface with the latest firmware, follow these steps:

- Visit www.altec.com/axis and select DOWNLOADS from the menu
- Download and save the firmware file (ending in 3.4.2.20240801) to a convenient location on your computer or mobile device
- Power your AXIS device
- Connect your computer or mobile device to AXIS and navigate to the Login page
- Select "Update Firmware" from the Guest Menu
- Browse to and select the locally saved firmware file (ending in 3.4.2.20240801) and follow instructions on the device

For additional support, please contact the AXIS support team at axis.support@altec.com.

Sincerely,
The AXIS Support Team